

#### **Automation related incidents**

Richard Batt
Australian Transport Safety Bureau

Australia's national transport safety investigator

### Overview

- Why investigate serious incidents?
- Two examples of serious incidents involving automated systems issues
- Research report of the flight deck automation working group

### Why investigate serious incidents?

- ICAO requires it
- Investigating a 'close call' provides a 'free lesson' in safety
- Essential for major accident preparedness

### Annex 13 - Chapter 5

5.1.2 The State of Occurrence <u>shall</u> institute an investigation into the circumstances of a serious incident when the aircraft is of a maximum mass of over 2,250 kg



### Automated systems issues

Worldwide, errors associated with the use and management of automatic flight systems have been identified as a contributing factor in more than 20% of approach and landing accidents.

Flight Safety Foundation ALAR Briefing Note 1.2 - Automation

### Automated systems issues

#### Automation surprise

- o What is it doing?
- Why is it doing that?
- What will it do next?



#### Mode error

A mode errors occurs when an operator loses track of which mode the device is in, or confuses which actions are appropriate in a particular mode

# Two serious incidents involving automated systems issues

- Boeing 777 descent below approach path
- Airbus A320 mishandled go-around

## ATSB Investigation AO-2011-086 Descent below approach path


- B777 low on approach to Melbourne, Vic
- Tower controller asked the crew to check their altitude and then instructed the crew to go-around
- Crew caught by surprise by the aircraft's automation



### VNAV mode change

On descent through 3,300 ft, the vertical navigation mode (VNAV) changed from speed (SPD) to path (PTH) and the aircraft pitched up to level flight to intercept the

required approach path



### Automation surprise

- The crew did not anticipate the aircraft pitching up and selected flight level change (FLCH) mode to continue the descent
- The crew thought the pitch up may have indicated a system fault and were unsure if VNAV would function normally if reselected



### Descent below approach path


- The aircraft was subsequently flown below the approach path, down to an altitude of 984 ft at 6.4 NM from the threshold
- When instructed to go around, there was a delay of about 50 seconds before the crew selected TOGA thrust and commenced to climb
- The aircraft subsequently landed safety


## ATSB Investigation AO-2007-004 *Mishandled go-around*

- A320 missed approach into Avalon, Vic, due to fog
- The crew mishandled the goaround and were unaware of the aircraft's flight mode
- The aircraft descended to within
   38 ft of the ground before climbing




### A320 thrust lever positions





### A320 Flight Mode Annunciator (FMA)



### Aircraft manufacturer's standard go-around procedure

A318/A319/A320/A321	STANDARD OPERATING PROCEDURES	3.03.23	P 1
FLIGHT CREW OPERATING MANUAL	GO AROUND	SEQ 110	REV 36
- THRUST LEVERS - ANNOUNCE	ree actions simultaneously :	GO AROUN	D – FLAPS" . PERFORM
· Check and annou	od by the CRE pitch command but noe the FMA: MAN TOGA, SRS, GA TRK.	_	T ONE STEP
- ANNOUNCE		POSIT	IVE CLIMB
- ORDER			"GEAR UP"
- L/G UP			SELECT
- CONFIRM/ANNOU	NCE	"GEAR	UP-FLAPS"
Nate : Consider re	tarding to CL detent, if TOGA thrust is not	required.	
	B		SELECT
	may be flown with both autopilots engag ges, AP 2 disengages.	ed. Whenev	er any other
<ul> <li>At go-around thru</li> </ul>	st reduction altitude (LVR CLB flashing	on FMA) :	
- THRUST LEVER	s		CL

### Operator's changed go-around procedure


A318 / A319 / A320 / A321	STANDARD OPERATING PROCEDURES	3.03.23	P1	
Flight Crew Operating Manual	GO AROUND	SEQ 110	REV 36	
GO AROUND	actions simultaneously			
			TOGA	
- ANNOUNCE		"GO AROUND - FLAPS"		
- ROTATION		PERFORM		
	to get a positive rate of climb, and establish Spitch command bar.	the required pit	ch attitude, a	
		RETRACT ONE STEP		
Announce "FLAPS" v				
		"POSITIVE CLIMB"		
- ORDER			GEAR UP	
- L/G UP			SELECT	
- CONFIRM/ANNOUNC	E			
Note: Consider retar	ding to CL detent. If TOGA thrust is not require	red.		
- ANNOUNCE FMA		"MAN TOGA, SRS, GA TRK"		
	, as required (minimum height 100-feet).		SELECT	
Note : Go-around me AP 2 disengag	y be flown with both autopilots engaged. When ies.	ever any other n	node engage	
<ul> <li>At go-around thru</li> </ul>	st reduction altitude (LVR CLB flashing on	FMA):		
	S			

### Airbus Safety First Magazine



### Airbus recommendations for go-around

- Firewall it!
- Thrust levers are also mode selectors
- Know your FMA at all times




### Operational Use of Flight Path Management Systems

Design, training and use of systems for flight path management

- Autopilot
- Autothrottle/autothrust
- Flight director
- Flight management systems (FMS)

Flight deck automation working group September 2013



# Findings related to automated systems

- Pilots relied on automated systems too much, reluctant to intervene
- Autoflight mode confusion errors continue to occur
- Use of information automation (eg calculation, information presentation) increasing
- FMS programming and usage errors continue to occur

# Recommendations related to automated systems

- Improved training and procedures for autoflight mode awareness
- Human centered design that,
  - Reduces the number and complexity of autoflight modes
  - Improves the feedback to pilots on mode transitions
  - Ensures that mode logic assists pilots' intuitive interpretation of failures and reversions

### Summary

- Automation related occurrences provide a good example of the potential safety benefit of investigating serious incidents
- Question Other similar occurrences in the APAC region?

### Thank you

Richard Batt richard.batt@atsb.gov.au