

FLIGHT INFORMATION SERVICES FOR SOMALIA (FISS)

AERONAUTICAL INFORMATION SERVICES
MOGADISHU INTERNATIONAL NOTAM OFFICE

P.O. BOX 46294, 00100

NAIROBI, KENYA

TEL/FAX: 254-20-7622775
AFS: HCMMYNYX
Email:ais@icao.unon.org
<http://www.icao.int/ESAF/FISS>

**NOTAM LIST
SERIES "A"**

The following NOTAM series "A" were still valid on 06 OCT 2017. NOTAM not included have either been cancelled, time expired or superseded by AIP supplements.

FIR		Subject
A0055/17	FROM 1707270840/ Perm caution advised due to unreliable Mogadishu FIC HF communication. pilots are requested to ensure appropriate mitigation measures including the use of SATCOM INMARSAT CODE 466601 on FIC Telephone Numbers +254202365679/+254207622774/+254207626028/+254202445632 and or rely via the airline operations unit or other ACFT or other ATS units as may be applicable.	mitigation measures due to Unreliable HF communication
A0065/17	From 1709041230/Perm. Recognition of the fact that Mogadishu FIR is Class G Airspace, where only Flight Information Services (FIS) is provided, pilots are to maintain a high level of alertness when transiting through the Mogadishu FIR RVSM airspace and take appropriate action to ensure safety of flight by maintaining continuous listening watch on VHF emergency frequency 121.5MHZ and IFBP frequency 126.9MHZ at all times.	FIR is Class G Airspace
A0039/17	From 1706061400/Perm Pilots experiencing HF radio communication failure while operating in Mogadishu FIR are requested to contact Mogadishu FIC on SATCOM using INMARSAT code 466601 on FIC telephone no +254202365679 or +254207622774 or +254207626028 or +254202445632 and/ or comply with normal procedures for Radio Communication Failure in accordance with ICAO provisions as may be applicable.	Radio communication failure procedure
A0073/17	From 1710020900/1801090900 Est. Operators should exercise extreme CTN and fully assess the potential risks to flight safety and security when planning or conducting ops into Mogadishu airport due to lack of information on armed conflict and the lack of adequate aeronautical information.	Potential risks to flight safety and security
A0030/17	From 1705031230/Perm UR400 ATS ROUTE BTN EGLOM AND MAV. EGLOM N004456E0472412 BRG 303/123 DEG DIST 147NM TO MOGDU N020024E0451736 BRG 303/123 DEG DIST240NM TO MAV N035624E0415151 LOWER/UPPER LIMIT 245/UNL. WIDTH RNAV10 CLASS G AIRSPACE BI-DIRECTIONAL BTN EGLOM AND MAV.ATS ROUTE UR400.	ATS Route
A0041/17	From 1706071300 / Perm. Aeronautical Information Publications except NOTAM are distributed online on FISS AIM Web Page: https://www.icao.int/ESAF/FISS/ Users will be advised on email once a new publication is uploaded on the site.	Availability of Somalia Aeronautical Publications
A0072/17	From 1710021230/1711021230. Checklist of NOTAM Series A inforce as of 02 OCT 2017.	NOTAM Checklist

AD

Aden Adde International Airport		Subject
A0018/17	From 1703140840/perm. Mogadishu international airport now renamed Aden Adde International Airport. ICAO location indicator (HCMM) remains unchanged.	Aden Adde International Airport
A0023/17	From 1703301400/perm. Operators intending to operate direct flight from Aden Adde International Airport (Mogadishu) to Jomo Kenyatta international airport (Nairobi) must request approval from director general of Somalia civil aviation and meteorological authority and file a flight plan. All flights departing from other airfields in Somalia are still required to go through Wajir airport for security vetting.	Direct Flights from HCMM to HKJK
A0070/17	From 1709261100/Perm Mogadishu ARO/BOF service AVBL and reachable on Tel No +252699777919 and +252619743013.	Aden Adde International Airport
A0057/17	From 1707311550/perm Aden Adde International Airport HRS of OPS changed to 0300-1900 UTC Daily effective 30/07/2017 AIP Supplement 38/2017 is Hereby Amended.	Aden Adde International Airport
Egal International Airport		
A0047/17	FROM 1707120900/Perm. Jet A1 Fuel Avbl At Bosaso International AP During Ops Hours. For Any Further Information, Contact The DS Aviation Fuel Company Limited. TEL:+252907796768 , E-MAIL: AHMED.HASHI@DSAVIATIONFUEL.COM , Website: Dsaviationfuel.Com	Jet A1 Fuel
A0053/17	From 1707260830/perm Pilots are Advised to Exercise Caution Due to Presence of Birds within the AD Circuit.	Presence of Birds
A0054/17	FROM 1707270830/perm. Air Traffic Controllers view of RWY 06 (Approx 300m Fm Thr Rwy 06) is obstructed. Pilots are advised to Exercise CTN when operating at the AD.	controllers view of RWY 06
Berbera Airport		
A0062/17	From 1709051430/1712051430 EST. Berbera Airport closed to all operations including emergency flights due to ongoing works.	Airport closed
Beletuen Airstrip		
A0063/17	FROM 1709041230/1712041230 EST. BELETUEN RWY closed for maintenance on Fridays and Saturdays only.	RWY closed
Garowe Airstrip		
A0064/17	FROM 1709041230/1712041230 EST. GAROWE Airstrip closed to all operations for construction from 06 Jun 2016. All operations shifted to CONOCO Airstrip. RWY 06/24 coordinates 082822N0486545E.	Garowe Air strip Closed

AIRAC AIP SUPPLEMENTS IN FORCE

2017: 41, 52

2016: 01

AIP SUPPLEMENTS IN FORCE

57, 56, 55, 54, 51, 50, 49, 48, 47, 45, 44, 43, 39, 38, 37, 36, 35, 34, 32, 31, 29, 26, 25, 24, 20, 19, 18, 17, 16, 15, 14, 13, 12, 11, 10, 08, 07, 06

AIC INFORCE: YEAR 2017: 02 01