Agenda Item 3: Develop an updated version of the Asia/Pacific ICD for AIDC

Text amendment to the AIDC ICD

SUMMARY

A number of ICAO references in the AIDC ICD need to be amended in line with changes in ICAO.

(Presented by Australia)

1. Background

- 1.1 During the last few years, a number of changes have been made to ICAO documentation and structure. These changes, as described below, need to be reflected in the AIDC ICD.
- 1.2 On the 1st November 2001, PANS-RAC Document 4444 and amendments thereto were superseded by the 14th edition of Document 4444. The document was also renamed PANS-ATM Document 4444.
- 1.3 In recent years, the ICAO Automatic Dependent Surveillance Panel (ADSP) was renamed the Operational Data Link Panel (OPLINKP).
- 1.4 In addition to the above points, the ICAO logo has been updated, and will need to be replaced.

2. Proposal

- 2.1 Update references to PANS-RAC in the following locations as follows:
 - Page 5, paragraph 4.2.1 Replace "Rules of the Air and Air Traffic Services (PANS-RAC, Doc 4444)" with "Air Traffic Management (PANS-ATM, Doc 4444)".
 - Appendix A-1 paragraph 1.1 Replace "(PANS-RAC 4444)" with "(PANS-ATM Doc 4444)"
 - Appendix E-1 paragraph 3 Replace "PANS-RAC 4444" with "PANS-ATM Doc 4444"

- 2.2 Update references to ADSP in the following locations as follows:
 - Table of Contents i-3 Replace "AIDC/ADSP Relationship" with "AIDC/OPLINKP AIDC Relationship".
 - Appendix A-1 paragraph 1.1 Replace "ICAO ADS panel" with "ICAO OPLINK Panel"
 - Appendix E-2 Table E-1 Replace AIDC/ADSP AIDC Relationship with "AIDC/OPLINKP AIDC Relationship"
 - Appendix E-2, E-3, E-4 Table E-1 Replace "ADSP AIDC Mandatory Data Field" with "OPLINKP AIDC Mandatory Data Field"
- 2.3 Update the ICAO logo
 - Cover page

Replace the ICAO



logo with the current ICAO logo.



3. Recommendation

3.1 Task Force members are invited to adopt the amendments proposed in this working paper for inclusion in the updated AIDC ICD.

* * *